


IMPORTANT SAFETY RECALL INFORMATION

December 2019

Dear Valued Customer:

In cooperation with the U.S. Consumer Product Safety Commission and Health Canada, Bass Pro is recalling MR. STEAK™ gas grills that have a fuel gauge attached to the regulator hose and a fuel line that is not attached to the side of the grill. The regulator hose can contact the bottom of the firebox and melt, which is a fire hazard.

Records indicate that you purchased a MR. STEAK grill between May 2017 and July 2019. The recalled grills have model numbers MS-4B-PG (four burner) and MS-5B-PG (five burner). The model number can be found on a label on the inside of the left compartment door or on the back of the grill. Only some versions of these models are subject to the recall, so please check to see if your grill has a fuel gauge and a fuel line that is not attached to the side of the grill.



Recalled — fuel gauge and fuel line not mounted to side of grill



Not recalled — no gauge attached to regulator assembly



Not recalled — fuel line mounted inside grill

If your grill has a fuel gauge attached to the regulator hose and the fuel line is not attached to the side of the grill stop using the grill and contact the MR. STEAK recall hotline to receive a free repair kit.

833-677-8325 or 833-MRSTEAK from 8 a.m. to 6 p.m. ET Monday through Friday, or online at mrsteak.com/repairpartskit

We apologize for any inconvenience.

Sincerely,
Bass Pro Shops